

Download Johnson Outboard Manual Release Valve

Outboard power trim manual release screw - How it works and where is it? Outboard power trim manual override. This is a 1993 and 1996 Evinrude 40 HP Outboard Camera used: Sony Alpha a6300 ...Outboard manufacturers include an alternative to the hydraulic tilt system for this exact scenario and it is called the manual tilt release valve. Mercury has the valve located on the right side of the engine bracket, (viewed as if you are driving the boat or standing behind the outboard motor). This Johnson 0387990 MANUAL RELEASE VALVE fits the following models and components: Johnson Outboard Parts by HP 70HP J70TLCIM 1981 POWER TILT & TRIM MODELS WITH "M" SUFFIX ONLY (EXPT 75 TRL) Johnson Outboard Parts by HP 70HP J70ELCIM 1981 POWER TILT & TRIM MODELS WITH "M" SUFFIX ONLY (EXPT 75 TRL) The manual release valve is the joker, the trickster of the tilt and trim system. All potential problems with the system may result from the manual release valve not being closed, or being partially closed, so make checking this valve the first step you take when going after a problem with the tilt and trim system.