

Download 2010 Audi Q5 Service Repair Manual Software

EU5 diesels from 2011 require AdBlue. 7-9-2012: Isolated one-off report of failure of the engine of a Q5 2.0 TFSI 211 S line, purchased fairly heavily loaded with extras in March 2011 for £36,500. Numerous electrical problems, but main fault excessive oil consumption. Pistons, conrods, oil rings and PCV case all replaced in July 2012. Audi ECU questions, Audi answers, Audi parts questions, Audi parts answers, automotive parts Audi will notify owners, and dealers will upload revised software to correct the issue, free of charge. This recall began November 2016. Owners may contact Audi customer service at 1-800-253-2834. VVDI2 Full Version comes with Basic Function + VW + BMW + Porsche+PSA+ AUDI Generation 5 Function+BMW OBD Function+BMW CAS4+ Functions +Tango + J2534, No Need to buy other Authorization.